68405

inspection or copying at room PL—401, located on the Plaza Level of the Nassif Building at the same address, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. You may also access this docket on the Internet at http://dms.dot.gov.

Copies of the complete ICRs are available through this docket on the Internet at http://dms.dot.gov and also from Commandant (G-SII-2), U.S. Coast Guard Headquarters, room 6106 (Attn: Barbara Davis), 2100 Second Street SW., Washington, DC 20593-0001. The telephone number is 202-267-2326.

FOR FURTHER INFORMATION CONTACT: Barbara Davis, Office of Information Management, 202–267–2326, for questions on this document. Dorothy Walker, Chief, Documentary Services Division, U.S. Department of Transportation, 202–366–9330, for questions on the docket.

DEPARTMENT OF TRANSPORTATION

Coast Guard
[USCG-1999-6581] - |

Collection of Information by Agency under Review by Office of Management and Budget

AGENCY: Coast Guard, DOT.

ACTION: Request for comments.

SUMMARY: In compliance with the Paperwork Reduction Act of 1995, 44 U.S.C. 3501–3520, the Coast Guard intends to request the approval of the Office of Management and Budget (OMB) for the renewal of two information Collection Requests (ICRs). These ICRs comprise: 1. Certificate of Discharge to Merchant Mariners, and 2. Recreational Boating Accident Reports. Before submitting the ICRs to OMB, the Coast Guard is asking for comments on the collections described below.

DATES: Comments must reach the Coast Guard on or before February 7, 2000.

ADDRESSES: You may mail comments to the Docket Management System (DMS) [USCG-1999-6581], U.S. Department of Transportation (DOT), room PL-401, 400 Seventh Street SW., Washington, DC 20590-0001, or deliver them to room PL-401, located on the Plaza Level of the Nassif Building at the same address, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The telephone number is 202-366-9329.

The Docket Management Facility maintains the public docket for this Request. Comments will become part of this docket and will be available for

Request for Comments

The Coast Guard encourages interested persons to submit written comments. Persons submitting comments should include their names and addresses, identify this document [USCG–1999–6581] and the specific ICR to which each comment applies, and give the reason(s) for each comment. Please submit all comments and attachments in an unbound format no larger than 8½ by 11 inches, suitable for copying and electronic filing. Persons wanting acknowledgment of receipt of comments should enclose stamped, self-addressed postcards or envelopes.

Information Collection Requests

1. *Title:* Certificate of Discharge to Merchant Mariners.

OMB Control Number: 2 115–0042. *Summary:* The collection of information requires a master or mate of a shipping company to submit information on merchant mariners to the U.S. Coast Guard that: (1) establishes their sea service time; (2) sets forth their qualifications for their original or upgrading their existing credentials; and (3) sets forth their qualifications for retirement or insurance benefits.

Need: Under Title 46 U.S.C. 10311, the information collected shows eligibility for merchant mariners' documents and tells the Maritime Administration the availability of mariners in a time of national emergency.

Respondents: Masters or mates of shipping companies and merchant mariners.

Frequency: On occasion.

Burden: The estimated burden is 4,500 hours annually.

2. *Title:* Recreational Boating Accident Report.

OMB Control Number: 2115-0010.

Summary: The information collected identifies possible manufacturers' defects in boats or equipment, helps develop boat manufacturing standards, helps develop safe-boating-education programs, and furnishes accident statistics.

Need: Title 46 U.S.C. 6102(a) requires the establishment of a uniform system for reporting marine casualties, with regulations prescribing casualties to be reported and the manner of reporting. The statute requires a State to compile and submit to the Coast Guard reports, information, and statistics on casualties reported to the State.

Respondents: Operators of recreational boats.

Frequency: On occasion.

Burden: The estimated burden is 4,232 hours annually.

Dated: November 24, 1999.

G. N. Naccara.

Rear Admiral, U.S. Coast Guard, Director of Information and Technology.

[FR Doc. 99–31646 Filed 12–6–99; 8:45 **am]**BILLING CODE **4910–15–U**

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

[Docket No. NHTSA-99-6034; Notice 2]

General Motors Corporation; Grant of Application for Decision of Inconsequential Noncompliance

General Motors Corporation (GM) of Warren, Michigan, has determined that a number of 1998 bi-fueled compressed natural gas (CNG) Chevrolet Cavaliers do not meet the requirements of S5.3 and S5.4 of 49 CFR 571.303, Federal Motor Vehicle Safety Standard (FMVSS) No. 303, "Fuel System Integrity of Compressed Natural Gas Vehicles," and has filed an appropriate report pursuant to 49 CFR Part 573, "Defects and Noncompliance Reports." GM has also applied to be exempted from the notification and remedy requirements of 49 U.S.C. Chapter 301—"Motor Vehicle Safety" on the basis that the noncompliance is inconsequential to motor vehicle safety.

Notice of receipt of the application was published, with a 30-day comment period, on August 6, 1999, in the **Federal Register** (64 FR 43011). NHTSA received no comments on this application during the 30-day comment period.

FMVSS No. 303, S5.3 requires that CNG vehicles shall be permanently labeled, near the vehicle refueling connection, with the information specified in S5.3.1 and S5.3.2.

S5.3.1 requires the statement:
"Service pressure kPa
(psig)," and S5.3.2 requires the statement "See instructions on fuel container for inspection and service life."

S5.4 requires that, when a motor vehicle is delivered to the first purchaser for purposes other than resale, the manufacturer shall provide the purchaser with a written statement of the information in S5.3.1 and S5.3.2 in the owner's manual, or, if there is no owner's manual, on a one-page document.

GM has notified us that in model year 1998, it manufactured 385 bi-fueled CNG Chevrolet Cavaliers that did not fully comply with the labeling requirements specified in 49 CFR 571.303. GM stated that the noncompliance consists of deviations from the wording required on the CNG vehicle label and in the owner's manual, These deviations are illustrated below.

GM explained that an out-of-date version of FMVSS No. 303, which did not contain specific requirements, was used by the supplier that prepared the label and owner's manual supplement. As a result, the CNG vehicle label applied near the refueling connection, and the owner's manual for the subject vehicles, did not contain the exact statements required by FMVSS No. 303, S5.3 and S5.4.

The required words and actual words used by GM are shown as follows:

FMVSS para- graph	Required Label Wording	'98 CNG Cavalier label wording
	SERVICE PRESSURE 24820 kPa (3600 psig) SEE INSTRUCTIONS ON FUEL CONTAINER FOR INSPECTION AND SERVICE LIFE.	
FMVSS para- graph	Required' owner's manual wording	'98 CNG Cavalier owner's manual wording
S5.4	SERVICE PRESSURE 24820 kPa (3600 psig)	This system operates at pressures up to 3600 PSI (24.8 MPa). (p. iv) The CNG fuel system is designed to use a fill pressure of 3,600 psi (24.8 MPa). (P. 6–3).
S5.4	SEE INSTRUCTIONS ON FUEL CONTAINER FOR INSPEC-	THE CNG FUEL TANK HAS A SERVICE LIFE OF 15 YEARS.

GM supported its application with the following arguments:

TION AND SERVICE LIFE.

GM believes that the labels and owner's manual supplement information provided with these vehicles are responsive and consistent with the rationale and intent of the requirements, even though the exact words required by the standard are not used. The actual labels and the owner's manual supplement provide equivalent information required by FMVSS 303, S5.3 and S5.4. The CNG refueling valve label clearly states the

operating pressure and refers the user to the owner's manual for information about tank service life. Both the refueling valve and the underhood labels include the service expiration date and the owners manual indicates the service life, inspection information, and provide a form to record the expiration date.

expiration date.

Additionally, virtually all CNG refueling stations incorporate an overfill protection system. Also, the subject vehicles are equipped with a CNG container validated up to 200 percent of the service pressure without

leakage as required by FMVSS 304, S7.2.2 for such containers. GM has not received any reports of injuries or property damage associated with overfilling of these vehicles and believes it is extremely remote that these deviations from FMVSS 303 label and owner's manual requirements could contribute to an injury or property damage incident.

For all of these reasons, GM believes that this noncompliance is inconsequential to motor vehicle safety. Accordingly, GM petitions that it be exempted from the